

ATTENTION

Citation III/650 operators



- 9914071-47 LH Windshield
- 9914071-48 RH Windshield
- 9914072-17 LH Side Cockpit Window
- 9914072-18 RH Side Cockpit Window
- PAS9914159-12 Cabin Window



Perkins Aircraft Windows is pleased to announce they have developed major overhaul and repair capabilities on all Citation III cockpit windows. Perkins can repair your cockpit windows to look like brand new for a fraction of the cost of replacing with Textron cockpit windows. And you won't have to drill and trim the frame!



Perkins Aircraft Windows

Testimonials

We used your services a couple months ago to have the acrylic pane replaced on the windshield of a Citation 650. It worked out great. Not only were we able to keep our customer's cost down by using a repaired windshield vs. a new one, but the installation was much quicker with the retainer already being fit and drilled for our aircraft. I will recommend, to all of our Citation 650 customers, to utilize this service. The windshield is good as a new one, and custom fit to the aircraft it came from.

- Jeremy Ficklin, Aircraft Services Manager
West Star Aviation - Grand Junction



PERKINS AIRCRAFT WINDOWS

2600 South Cherry Lane, Suite 162
Fort Worth, TX 76116

817-877-1966 800-880-1966

817-877-4339 Fax

sales@perkinsaircraft.com

Thank you for your support and developing a process to replace the acrylic windshield panes in our Citation 650. Your process saved us thousands of dollars, labor and down time. The repaired windshield quality was very good. The windows dropped in with no trimming and look great. I would recommend your repair process over new windows to anyone needing windshields.

- Jeff Ostwinkle
Baker Aviation

